

Description of the vehicle

Manufacturer: Alfa Romeo
Model: Alfa 159
First admission: 07.07.2008
Mileage: 226000
Service book yes/no: No
Emission standard: Euro4
Color: Black
Metallic Paint: No
Seating: 5
Gears: Manual
Paid tax: No

Body type: EstateCar
Number of doors: 5
Accident free yes/no: No
Engine type: Diesel
Capacity: 1900
Performance: 120
Severely damaged: No
Air conditioning: No a/c or automatic a/c

Timing belt replacement at km: 190000

Condition:

<https://suchen.mobile.de/fahrzeuge/auto-inserat/alfa-romeo-alfa-159-159-sportwagon-1-9-jtdm-8v-dpf-rohrdorf/252975095.html?lang=de>

Equipment

Comfort equipment: No
Power windows: Yes
Leather seats: No
Sunroof: No
Heated seats: No
Central locking: No
Alarm system: No

Electric adjustable seats: No
Height adjustable steering wheel: No
Automatic climate control: Yes
Parking sensors: No
Power steering: No
Cruise control: Yes
ABS: Yes
Alloy wheels: No

All-wheel drive: No
Heater: No
Xenon headlights: No
Immobilizer: No
Towbar: No

Stability Control (ESC): No
Navigation system: No
CD changer: No
Catalytic converter: No
Tuning: No

Damage

Front damage: Unspecified



Roof damaged: Unspecified



Damaged left front side: Unspecified



Left side front door damaged: Unspecified



Left side rear door damaged: Unspecified



Damaged left rear side: Unspecified



Damage page 2

Tail damaged: Unspecified



Damaged right front side: Unspecified



Right side front door damaged: Unspecified



Right side rear door damaged: Unspecified



Damaged right rear side: Unspecified

